

# Arizona Department of Environmental Quality

## Water Quality Compliance Assurance Unit

1110 W. Washington Street, 5415B-1

Phoenix, AZ 85007

### Drinking Water Compliance Status Report

**Public Water System Name:** City of Tucson Water Department

**Public Water System ID #:** 10-112

**Overall Compliance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

**Monitoring and Reporting Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
Comments:

**Operation and Maintenance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: 06/18/2003

#### **Administrative Orders:**

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

#### **System information:**

Number of Points of Entry 130 Number of Sources 200 Population Served 668,000

Service Connections 191,019 Initial Monitoring Year 1995 Initial MAP Year N/A

**Evaluation completed by:** John Calkins, Supervisor, Water Quality Compliance Assurance

**Phone:** (602) 771-4651 **Date:** 03/04/04

Based upon data submitted by the water system, ADEQ has determined this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.